

Survey Area

Septic System

Curb

-E-

Electric

-X-

Fence

-G-

Gas

-C-

Telecom Cable

-FO-

Telecom Fiber Optic

-T-

Telecom Telephone

-W-

Water

EOI

End of Trace

Electric Outlet

X

Other

Sign

T

Telecom Pull Box

W

Water Well

Gas Marker Post

FO

Fiber Optic Pullbox

0153060

Feet

1 inch = 32 feet

Telephone Line Crosses
Fence. Signal is Lost

No Scanning
Performed Inside
Pool Area

Septic System with
Septic Tank and
Three Infiltration Tanks

Figure 1: Subsurface Utility Survey Results

Washington Crossing, PA
Upper Makefield Township
Bucks County, PA

RETTEWSM

RETTEW Field Services, Inc.
5031 Richard Lane, Suite 111, Mechanicsburg, PA 17055
Phone (717) 697-3551

SURVEY DATE:	3/14/2025
PROJECT No:	0963003386
REVIEWED BY:	DEM
DRAWN BY:	SHC
DATE:	03/18/2025
FIGURE No:	1 of 1

Path: Z:\Shared\Projects\09630\0963003386 - SL - Washington Crossing Well Complaints\SUE\GIS\Glenwood GIS\Glenwood GIS.aprx